



ASIX USB-to-LAN Application Macintosh OS X 10.5 Driver Release Note

Revised Date: 2008/06/13

ASIX Electronics is the market leader of the USB 2.0 to Fast/Gigabit Ethernet controllers solutions, we provide the AX88178/AX88772A/AX88772 USB-to-LAN standard drivers for customers to evaluate the functionality of AX88178/AX88772A/AX88772 demo boards.

Apple MacBook Air OSX 10.5 system already supports the following AX88178/AX88772A/AX88772 USB-to-LAN solutions.

Vendor	Model Name	VID	PID	Comments
ASIX Electronics Corp.	AX88178	0B95h	1780h	
ASIX Electronics Corp.	AX88772A	0B95h	772Ah	
ASIX Electronics Corp.	AX88772	0B95h	7720h	
Apple	Apple USB Ethernet Adapter	05ACh	1402h	
Linksys	USB200M	13B1h	0018h	
D-Link Corp.	DUB-E100 Fast Ethernet	2001h	3C05h	
Linksys	USB1000	1737h	0039h	
Belkin Components	F5D5055	050Dh	5055h	
MelCo., Inc.	USB Gigabit Ethernet	0411h	006Eh	
I-O Data Device, Inc.	ETG-US2	04BBh	0930h	

The other customers should contact with ASIX Sales (sales@asix.com.tw) for further driver support.

Note: End user should get proper drivers from the manufacturer of your AX88178/AX88772A/AX88772 device.



ASIX Electronics Corporation.

**4F, No.8, Hsin Ann Rd., Hsinchu Science Park,
Hsinchu, Taiwan, R.O.C.**

TEL: +886-3-5799500

FAX: +886-3-5799558

Email: support@asix.com.tw

Web: <http://www.asix.com.tw>